



$$\begin{aligned} Ra = & R20 + R21 = 1533R \\ Rb = & R22 = 220R \\ y_{out} = & \langle Ra/Rb + 1 \rangle * 1, 25V + Rak500ua \end{aligned}$$

DE0508

+5V : +10V PSU YUNA N2PK USB

Use Rev 1.03 29.06.2011 Page 1